

2008-10 F250 – F350 5.4L & 6.8L Engines

Known Early Failure of Catalyst

Subject: Cracking or melting of the ceramic substrate.

Model(s): F250 & F350

Year: 2008-10 Using our part number 19346

Advisory: In some of the effected vehicles, certain operating conditions can cause the catalyst substrate to crack or melt. This can cause symptoms including but not limited to, audible noise from the catalyst Y-pipe and or malfunction indicator lamp illumination.

All US Ford Dealers have extended the warranty of this OE part to 11 years or 120,000 miles. The service action in addition to the replacement of this Converter is a reprogramming of the Powertrain Control Module (PCM).

Additional Help: Available from Davico Technical Assistance at 800-422-6046
Ford CSP 10M05 Supplement #1