

Your Source for Hard - to - Find Catalytic Converters

Technical Advisory Bulletin

March 2013 TAB16043-031813

16043

Various Mercedes Benz Applications

Subject: Part appears different from original.

Model(s): 300SE

Year: 2000-2010

Condition: Front resonators deleted

Update: Part number 16043 may appear to be different from the original design but has been

updated to work on this vehicle platform. The front assemblies have been replaced with a higher efficiency rear Converter Body so that the front units could be deleted

for cost control.

Additional Help: Available from Davico Technical Assistance at 800-422-6046

95 Brook Street New Bedford, MA 02746

United States

© Davico Inc. 2012

Phone: (800)422-6046 Fax: (508)998-8749

E-Mail: contactdavico@davicomfg.com

Web Site: www.davicomfg.com